

Citism@rt.Residence Project
Bi-weekly progress photos updated on 23 May 2008



Pict 01 : Side View



Pict 02 : Front View



Pict 03 : 1st Floor



Pict 04 : Lift Lobby , Tiling works and Aluminium frame



Pict 05 : Stock yard area



Pict 06 : Stock yard area




Pict 07 : 1st FL Elevator



Pict 08 : Ceiling Paint above Lift lobby



Pict 09 : Stair to 2nd Floor



Pict 10 : 2nd Floor



Pict 11 : 2nd FL Elevator



Pict 12 : Tiling works infront of Elevator

Citism@rt.Residence Project
Bi-weekly progress photos updated on 23 May 2008



Pict 13 : Corridor view



Pict 14 : Stair to 3rd Floor



Pict 15 : Ceiling painting and tiling works



Pict 16 : Air Condition and electricity testing



Pict 17 : Shaft door painting works



Pict 18 : M&E Door installation



Pict 19 : Shower screen view



Pict 20 : Terrace View



Pict 21 : Toilet cabinet and accessories



Pict 22 : Corridor Tiling works



Pict 23 : Laminated flooring



Pict 24 : Laminated Flooring

Citism@rt.Residence Project
Bi-weekly progress photos updated on 23 May 2008



Pict 25 : 3rd Floor



Pict 26 : Unit 301 , Tiling works



Pict 27 : Secondary paint



Pict 28 : Stair finishing to 4th Floor



Pict 29 : Corridor Tiling works



Pict 30 : Shaft Door painting



Pict 31 : M&E Door installation



Pict 32 : Tiling work at Corridor



Pict 33 : Laminated flooring



Pict 34 : Aluminium Door and Windows



Pict 35 : Wooden door final painting



Pict 36 : 4th Floor

Citism@rt.Residence Project
Bi-weekly progress photos updated on 23 May 2008



Pict 36 :



Pict 37 : Stair to 4th Floor



Pict 38 : Laminated flooring



Pict 39 : Kitchen and 2nd painting



Pict 40 : Shower screen installation



Pict 41 : M&E Door installation



Pict 42 : Stair Finishing to 3rd Floor



Pict 43 : Corridor Tiling works



Pict 44 : Laminated Flooring



Pict 45 : Shower Screen



Pict 46 : Toilet Cabinet



Pict 47 : Air Condition system



Pict 48 : 5th Floor



Pict 49 : 5th Floor Elevator



Pict 50 : Stair to 6th Floor



Pict 51 : Corridor Tiling works



Pict 52 : Ceiling works



Pict 53 : Air Condition system



Pict 54 : Ceiling above toilet



Pict 55 : Shaft door installation



Pict 56 : Door installation



Pict 57 : Door and door frame installation



Pict 58 : Sanitary ware and protection



Pict 59 : Corridor view

Citism@rt.Residence Project
Bi-weekly progress photos updated on 23 May 2008



Pict 60 : Corridor view



Pict 61 : Tiling works and general view



Pict 62 : Ceiling fan installation



Pict 63 : Ceiling works above toilet



Pict 64 : Ceiling works and Fans



Pict 65 : Ceiling works and Fans



Pict 66 : Aluminium door frame installation



Pict 67 : Aluminium door frame installation



Pict 68 : Aluminium door frame installation



Pict 69 : Door installation



Pict 70 : Corridor Tiling works



Pict 71 : 6th Floor

Citism@r.Residence Project
Bi-weekly progress photos updated on 23 May 2008



Pict 72 : Stair to 7th Floor



Pict 73 : Elevator 6th Floor



Pict 74 : Ceiling works and Air condition works



Pict 75 : Primary paint



Pict 76 : Wiring work



Pict 77 : Sanitary installation



Pict 78 : Corridor tiling works



Pict 79 : Shaft door installation



Pict 80 : M&E Piping works



Pict 81 : Ceiling works and Air condition



Pict 82 : Ceiling works and Air condition



Pict 83 : Electrical works

Citism@rt.Residence Project
Bi-weekly progress photos updated on 23 May 2008



Pict 84 : Ceiling frame and electric wiring



Pict 85 : Air condition installtion



Pict 86 : Corridor Tiling works



Pict 87 : Primary painting works



Pict 88 : Ceiling works and primary paint



Pict 89 : External Plastering works



Pict 90 : Flooring works of stair down to 5th Floor



Pict 91 : 7th Floor



Pict 92 : Plastering and other works



Pict 93 : Stair to 7th floor unit



Pict 94 : Primary paint and piping works



Pict 95 : Door frame and brick works

Citism@rt.Residence Project
Bi-weekly progress photos updated on 23 May 2008



Pict 96 : Surface preparation for flooring works



Pict 97 : Plastering work above ceiling works



Pict 98 : Ceiling frame and piping works



Pict 99 : Ceiling frame works



Pict 100 : Primary painting



Pict 101 : Air condtion system and ceiling frame



Pict 102 : Tiling works in Toilet



Pict 103 : 8th Floor



Pict 104 : Elevator preparation work



Pict 105 : Stair to Swiming pool area



Pict 106 : Brick works and plastering works



Pict 107 : Corridor general view

Citism@rt.Residence Project
Bi-weekly progress photos updated on 23 May 2008



Pict 108 : Primary painting



Pict 109 : Tiling works in toilet



Pict 110 : Air condition installtion



Pict 111 : Wooden door frame and primary paint



Pict 112 : Brick and plastering works



Pict 113 : Wall Tiling works



Pict 114 : Wall plastering works



Pict 115 : Swiming pool and pool deck



Pict 116 : General view and skeeding surface preparation



Pict 117 : Blockout for stair lamp to 8th floor



Pict 118 : General of view



Pict 119 : Swiming pool tiling works

Citism@rt.Residence Project
Bi-weekly progress photos updated on 23 May 2008



Pict 120 : Jacuzzi Bench works



Pict 121 : Planter box and primary paint



Pict 122 : Swimming pool tiling works



Pict 123 : Jacuzzi Bench works



Pict 124 : Light weight brick works and plastering



Pict 125 : Plastering works



Pict 126 : General view



Pict 127 : Brick works



Pict 128 : Primary paint around stair



Pict 129 : Fire exit stair case 7th Floor



Pict 130 : Fire exit stair case 6th to 7th Fl



Pict 131 : Fire exit stair case 6th Floor

Citism@rt.Residence Project
Bi-weekly progress photos updated on 23 May 2008



Pict 132 : Fire exit stair case 5th to 6th FI



Pict 133 : Fire exit stair case 5th Floor



Pict 134 : Fire exit stair case 5th to 4th FI



Pict 135 : Fire exit stair case 4th Floor



Pict 136 : Fire exit stair case 4th to 5th FI



Pict 137 : Fire exit stair case 3rd Floor



Pict 138 : Fire exit stair case 3rd to 4th FI



Pict 139 : Fire exit stair case 3rd to 2nd FI



Pict 140 : Fire exit stair case 2nd Floor



Pict 141 : Fire exit stair case 2nd to 3rd FI