

Citism@rt.residence Project
Bi-weekly progress photos updated on 21 July 2008



Pict No.01 : Front View



Pict No.02 : Side View



Pict No.03 : Side View



Pict No.04 : 1st Floor



Pict No.05 : Garbage Area



Pict No.06 : Transformer



Pict No.07 : Balcony hand rail fabrication.



Pict No.08 : Stockyard area



Pict No.09 : Aluminium sliding door and Contractor office



Pict No.10 : General view



Pict No.11 : Door installation of MDB Room



Pict No.12 : Cement plastering works

Citism@rt.residence Project
Bi-weekly progress photos updated on 21 July 2008



Pict No.13 : General view




Pict No.14 : Wall decoration behind project



Pict No.15 : Fire exit ladder 1st-2nd floor



Pict No.16 : Door frame and 1st Toilet



Pict No.17 : Tiling works in 1st Toilet



Pict No.18 : Tiling works in 1st Toilet



Pict No.19 : 1st Office view



Pict No.20 : Storage room under staircase



Pict No.21 : 1st Office view



Pict No.22 : Wiring works



Pict No.23 : 1st Floor in front of elevator



Pict No.24 : Staircase 1st to 2nd floor

Citism@rt.residence Project
Bi-weekly progress photos updated on 21 July 2008



Pict No.25 : 2nd Floor



Pict No.26 : 2nd Floor infront of elevator



Pict No.27 : Surface preparation works for Unit 201



Pict No.28 : Surface preparation works for Unit 201



Pict No.29 : General view



Pict No.30 : Corridor general view



Pict No.31 : 2nd Bedroom General view



Pict No.32 : Living area



Pict No.33 : Balcony Hand railing installation



Pict No.34 : Master bedroom general view



Pict No.35 : Water pipe shaft door



Pict No.36 : Piping works above janitor room

Citism@rt.residence Project
Bi-weekly progress photos updated on 21 July 2008



Pict No.37 : Corridor general view



Pict No.38 : Block out for aluminium windows



Pict No.39 : Living area general view



Pict No.40 : Kichen area



Pict No.41 : WG1 Fixed windows beside Janitor room



Pict No.42 : WG1 Fixed windows beside Janitor room



Pict No.43 : Stair to 3rd Floor



Pict No.44 : 3rd Floor



Pict No.45 : 3rd Floor infront of elevator



Pict No.46 : Stair to 4th Floor



Pict No.47 : Corridor general view



Pict No.48 : Water pipe shaft door

Citism@rt.residence Project
Bi-weekly progress photos updated on 21 July 2008



Pict No.49 : Master bedroom general view



Pict No.50 : Balcony View



Pict No.51 : General view



Pict No.52 : Cabinet above Water sink



Pict No.53 : Shower screen



Pict No.54 : WG1 Fixed windows beside Janitor room



Pict No.55 : Corridor general view



Pict No.56 : Living area general view



Pict No.57 : Master bedroom general view



Pict No.58 : Balcony view



Pict No.59 : Balcony view



Pict No.60 : 4th Floor

Citism@rt.residence Project
Bi-weekly progress photos updated on 21 July 2008



Pict No.61 : Stair to 5th Floor



Pict No.62 : Living area general view



Pict No.63 :



Pict No.64 : Master bedroom general view



Pict No.65 : Shower screen



Pict No.66 : Cabinet above water sink



Pict No.67 : Cabinet under sink



Pict No.68 : Corridor General view



Pict No.69 : Water pipe shaft door



Pict No.70 : Living area general view



Pict No.71 : Piping works above janitor room



Pict No.72 : Corridor General view

Citism@rt.residence Project
Bi-weekly progress photos updated on 21 July 2008



Pict No.73 : WG1 Fixed windows beside Janitor room



Pict No.74 : 5th Floor



Pict No.75 : Living area general view



Pict No.76 : Kitchen Area general view



Pict No.77 : Master Bedroom



Pict No.78 : Balcony View



Pict No.79 : Balcony View



Pict No.80 : Corridor view



Pict No.81 : Stair to 6th Floor



Pict No.82 : Floor tiling works



Pict No.83 : Water pipe shaft door



Pict No.84 : Floor tiling works

Citism@rt.residence Project
Bi-weekly progress photos updated on 21 July 2008



Pict No.85 : WG1 Fixed windows beside Janitor room



Pict No.86 : Living area general view



Pict No.87 : Balcony Ceiling works



Pict No.88 : Fire exit door



Pict No.89 : 6th Floor



Pict No.90 : Stair to 7th Floor



Pict No.91 : Corridor general view



Pict No.92 : Living area general view



Pict No.93 : Kitchen area



Pict No.94 : Master bedroom general view



Pict No.95 : Kitchen area



Pict No.96 : Living area general view

Citism@rt.residence Project
Bi-weekly progress photos updated on 21 July 2008



Pict No.97 : Master bedroom general view



Pict No.98 : Corridor general view



Pict No.99 : Living area general view



Pict No.100 : Studio Unit general view



Pict No.101 : Floor tiling works for Living area



Pict No.102 : Master bedroom general view



Pict No.103 : Stair to 7th Floor



Pict No.104 : Stair to 7th Floor



Pict No.105 : 7th Floor



Pict No.106 : Corridor general view



Pict No.107 : Door paint



Pict No.108 : Ceiling frame and plastering

Citism@rt.residence Project
Bi-weekly progress photos updated on 21 July 2008



Pict No.109 : Kensai and outside works



Pict No.110 : Balcony view



Pict No.111 : Ceiling plastering works



Pict No.112 : Floor tiling works



Pict No.113 : Ceiling plastering works



Pict No.114 : Stair to 8th floor



Pict No.115 : Ceiling plastering works



Pict No.116 : Ceiling frame works



Pict No.117 : Floor tiling works



Pict No.118 : Air conditioning systems



Pict No.119 : Corridor general view



Pict No.120 : Living area

Citism@rt.residence Project
Bi-weekly progress photos updated on 21 July 2008



Pict No.121 : Master bedroom general view



Pict No.122 : General view



Pict No.123 : WG1 Fixed windows beside Janitor room



Pict No.124 : 8th Floor



Pict No.125 : 8th Floor in front of elevator



Pict No.126 : Stair to Swimming pool & Pool deck



Pict No.127 : Corridor General view



Pict No.128 : Water pipe shaft door



Pict No.129 : General view of stair



Pict No.130 : General view



Pict No.131 : Corridor General view



Pict No.132 : WG1 Fixed windows beside Janitor room

Citism@rt.residence Project
Bi-weekly progress photos updated on 21 July 2008



Pict No.133 : Surface preparation for Tiling works



Pict No.134 : General view



Pict No.135 : Fire exit door



Pict No.136 : Surface preparation for Tiling works



Pict No.137 : Rectify work of drainage pipe



Pict No.138 : Rectify work of drainage pipe



Pict No.139 : Balcony view



Pict No.140 : Natural stone decoration



Pict No.141 : Natural stone decoration



Pict No.142 : Sand stone works



Pict No.143 : Sand stone works



Pict No.144 : Sand stone works

Citism@rt.residence Project
Bi-weekly progress photos updated on 21 July 2008



Pict No.145 : Wall tiling works



Pict No.146 : Sand stone works



Pict No.147 : Kenzai decoration



Pict No.148 : Surface preparation



Pict No.149 : Swimming pool general view



Pict No.150 : Jacuzzi Bench tiling works



Pict No.151 : Planter box



Pict No.152 : 8th Floor Fire exit area



Pict No.153 : Handrailing to 7th Floor



Pict No.154 : Ceiling works above fire exit area



Pict No.155 : 7th Floor



Pict No.156 : Handrailing works to 6th floor

Citism@rt.residence Project
Bi-weekly progress photos updated on 21 July 2008



Pict No.157 : 6th Floor



Pict No.158 : Handrailing to 6th floor



Pict No.159 : 5th floor



Pict No.160 : Handrailing to 4th floor



Pict No.161 : 4th floor



Pict No.162 : Handrailing to 3rd floor



Pict No.163 : 3rd floor



Pict No.164 : Handrailing to 2nd floor



Pict No.165 : 2nd floor



Pict No.166 : Hand railing to 3rd floor



Pict No.167 : Hand railing to 1st floor



Pict No.168 : Ladder to 1st floor