

Biweekly Photo progress , Updated on 31 March 08



Picture 1: Updated photo of Side of



Picture 2: Updated photos of In front of



Picture 3: 1st Floor



Picture 4: Stock yard Area



Picture 5: JWS Temporary site office



Picture 6: Stock yard area



Picture 7: Update staircase



Picture 8: 2nd Floor



Picture 9: In front of Mockup Unit B2-A



Picture 10: Corridor Picture



Picture 11: Corridor Picture



Picture 12: Mockup Unit & Meeting room



Picture 13: Wooden door frame and



Picture 14: Aluminium Door & window



Picture 15: Aluminium Door & window

Biweekly Photo progress , Updated on 31 March 08



Picture 16: Rest room



Picture 17: Aluminium door & windows



Picture 18: Primary internal painting



Picture 19: Door & Aluminium Frame



Picture 20: Duct and Wiring system at



Picture 21: Internal Painting



Picture 22: Duct and Wiring system at



Picture 23: 3rd Floor



Picture 24: Internal Painting



Picture 25: Internal Painting



Picture 26: Duct and Wiring system at



Picture 27: Toilet area



Picture 28: Corridor and Shaft room



Picture 29: Corridor



Picture 30: Toilet Area

Biweekly Photo progress , Updated on 31 March 08



Picture 31: Aluminium door frame and



Picture 32: Aluminium door frame and



Picture 33: Corridor Area



Picture 34: Aluminium and Door frame



Picture 35: Aluminium and Door frame



Picture 36: Wooden door frame and



Picture 37: Ceiling block out for Air



Picture 38: 4th Floor



Picture 39: Ceiling frame picture



Picture 40: Air condition



Picture 41: Wooden door frame and



Picture 42: Ceiling works installation



Picture 43: Toilet Tiling and Sanitary ware



Picture 44: Tiling works at Kitchen Area



Picture 45: Tiling works at Kitchen Area



Picture 46: Door frame rendering



Picture 47: 5th Floor



Picture 47: Tiling works at Kitchen Area



Picture 48: Tiling works at Kitchen Area



Picture 49: Wall and Floor tiling work in



Picture 50: Surface Preparing for Terrace



Picture 51: Duct piping and wiring



Picture 52: Corridor Picture



Picture 53: Ceiling frame installation



Picture 54: Wall Tiling in Toilet



Picture 55: Corridor Area



Picture 56: Wall Tiling in Toilet



Picture 57: Wall Tiling in Toilet



Picture 58: Electricity wire installation at



Picture 59: Ceiling frame installation



Picture 60: 6th Floor



Picture 61: Brick wall and plastering



Picture 62: Brick wall and plastering



Picture 63: Duck installation at Corridor



Picture 64: Brick wall and plastering



Picture 65: Brick wall and plastering



Picture 66: 7th Floor



Picture 67: Brick wall and plastering



Picture 68: Structure work and



Picture 69: Corridor area



Picture 70: Duck piping and wiring



Picture 71: Brick wall works



Picture 72: 8th Floor



Picture 73: Stair structure to Swimming



Picture 74: Brick wall and plastering

Biweekly Photo progress , Updated on 31 March 08



Picture 75: Brick wall and plastering



Picture 76: Structure works at Pool deck



Picture 77: Swimming pool structure works



Picture 78: Swimming pool



Picture 79: Structure works



Picture 80: Structure works under